


1985 RX-7 & 1986 B2000

SUBJECT Manually Tuned Radio (MTR) Modifications.

DESCRIPTION

Station preset pushbuttons on some 1985 RX-7s and 1986 B2000s equipped with manually tuned radio (MTR) may malfunction due to the buttons breaking. In order to prevent this problem, the pushbuttons have been modified beginning with VINs listed below.



NOTE:

This modification was NOT applied to the 1985 RX-7 because production had already ceased for this vehicle.

VIN OF PRODUCTION CHANGE

1986 B2000 Short Bed:	JM2UF111		
Long Bed:	JM2UF211	G0587246	August, 1985
Cab Plus:	JM2UF311		

PARTS INFORMATION

0000 81 3015 MTR (Clarion) for 1985 RX-7, 1986 B2000

NOTE:

The part number for the MTR radio has NOT been changed. However, the modified push buttons have been installed on all exchange radios.

WARRANTY INFORMATION

	(All areas except MMA-C)	(MMA-C only)
Customer Comment Code:	7E	B2
Damage Code:	05	AD
Process No:	J5-002A	
Part No. of Main Cause:	0000-81-3015	
Operation No:	66860X-R-X	
Labor Hour:	0.7 Hr.(1986 B2000)	0.5 Hr.(1985 RX-7)