

GLC, 626, RX-7 & B2000


SUBJECT Speed Nut for Ignition Key Switch.

DESCRIPTION

The speed nut for fixing the key-less switch to the ignition key cylinder housing has been established as a service part. If the replacement of the ignition key switch is necessary, please use the new speed nut to secure the key-less switch.

PARTS INFORMATION

PART NUMBER		DESCRIPTION
NEW	OLD	
BC46 66 158	-	Speed Nut



73

- Using a felt tip marker pen, make a small dot, approximately 1/4" diameter on the underside of the lower column cover to show that the repair has been completed.

WARRANTY INFORMATION

Customer Comment Code: 99
 Damage Code: 99
 Process No: A5-008A
 Part No. of Main Cause: UB39 66 122
 Operation No: XX0064-RX
 Labor Hour: 0.5 Hr.

